



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of: Blandy

Serial No.: 09/671,875

Filed: September 28, 2000

For: Apparatus and Method for Creating Instruction Bundles in an Explicitly Parallel Architecture § Group Art Unit: 2183

§ Examiner: Tsai, Henry

§ Attorney Docket No.: AUS9-2000-0587-US1

§

Certificate of Mailing Under 37 C.F.R. § 1.8(a)

I hereby certify this correspondence is being deposited with the United States Postal Service as First Class mail in an envelope addressed to: Commissioner for Patents, P. O. Box 1450, Alexandria, VA 22313-1450 on May 25, 2006.

By: Well Whitton

Dell Whitton

TRANSMITTAL DOCUMENT

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 Certificate
JUN 0 2 2006

of Correction

Sir:

ENCLOSED HEREWITH:

- Request for Certification of Correction of Office Mistake;
- Certificate of Correction; and
- Our return postcard.

No fees are believed to be necessary. If, however, any fees are required, I authorize the Commissioner to charge these fees which may be required to IBM Corporation Deposit Account No. 09-0447.

Respectfully submitted,

Duke W. Yee

Registration No. 34,285

YEE & ASSOCIATES, P.C.

P.O. Box 802333

Dallas, Texas 75380 (972) 385-8777

ATTORNEY FOR APPLICANT

THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of: Blandy

Serial No.: 09/671,875

MAY 3 0 2006

Filed: September 28, 2000

For: Apparatus and Method for Creating Instruction Bundles in an Explicitly Parallel Architecture S Group Art Unit: 2183

§ Examiner: Tsai, Henry

Attorney Docket No.: AUS9-2000-0587-US1

§

Certificate of Mailing Under 37 C.F.R. § 1.8(a)

I hereby certify this correspondence is being deposited with the
United States Postal Service as First Class mail in an envelope
addressed to: Commissioner for Patents, P.O. Box 1450,
Alexandria, VA 22313-1450 on May 25, 2006.

By: Dell Whitton

REQUEST FOR CERTIFICATE OF CORRECTION OF OFFICE MISTAKE

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

We would like to request a Certificate of Correction of Office Mistake with regard to issued patent 6,912,647 B1.

There is an error with respect to the following data:

Col. 10, line 7: after "group" insert

- -, wherein creating one or more instruction bundles is performed in view of one or more of the following rules:
 - 1) instructions of the same instruction type will preserve there original order;
 - 2) branches will normally appear only in the final bundle of an instruction group;
- 3) for architectures where a number of M execution units is equal or less than a number of concurrent bundles, MM templates will only be used when there are three or fewer instructions remaining in the group;
- 4) instructions are taken in order of their flexibility in terms of where that instruction can be placed in the available bundle types; and
 - 5) MBB and BBB templates are avoided when only a single B instruction remains.-

Col. 10, line 65: after "group" delete

"; and

means for dynamically creating one or more instruction bundles based on the number of each possible type of instruction in the one or more instructions of the instruction group".

Col. 12, line 37: after "claim" delete "25" and insert -27-.

No fees are believed to be necessary. If, however, any fees are required, I authorize the Commissioner to charge these fees which may be required to IBM Corporation Deposit Account No. 09-0447.

Respectfully submitted,

Duke W. Yee

Registration No. 34,285

YEE & ASSOCIATES, P.C.

P.O. Box 802333

Dallas, Texas 75380

(972) 385-8777

ATTORNEY FOR APPLICANT

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,912,647 B1

DATED

: Jun. 28, 2005

INVENTOR(S) : Blandy

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 10, line 7: after "group" insert

- -, wherein creating one or more instruction bundles is performed in view of one or more of the following rules:
- 1) instructions of the same instruction type will preserve there original order,
- 2) branches will normally appear only in the final bundle of an instruction group;
- 3) for architectures where a number of M execution units is equal or less than a number of concurrent bundles, MM templates will only be used when there are three or fewer instructions remaining in the group;
- 4) instructions are taken in order of their flexibility in terms of where that instruction can be placed in the available bundle types; and
- 5) MBB and BBB templates are avoided when only a single B instruction remains.-

Col. 10, line 65: after "group" delete

": and

means for dynamically creating one or more instruction bundles based on the number of each possible type of instruction in the one or more instructions of the instruction group".

Col. 12, line 37: after "claim" delete "25" and insert -27-.

MAILING ADDRESS OF SENDER:

PATENT NO:

6,912,647 B1

IBM Corporation, IP Law Dept. 11400 Burnet Road Austin, TX 78758

No. of additional copies

0

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USFTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to ். கொண்க கண்கள் நடிகளிலு கரி வக்கின்று கோட்களுள்ள வதுகோண்டி form to the USPTO. Time will vary depending upon the individual case. Any comments on the smount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Peteril and Trademark Office. U.S. Department of Commerce. P.O. Box 1459. Alexandria, VA 22312 1459. DO NOT SEND FEES OR COMPLETED 114 DERIG 41FE TA LLIIS-17-01.

if you need assistance in completing the form, call 1 566 PTO 0100 and saled option 2.